

ORIGINATOR: COLIN MOOKS

DATE : 22.10.84

PART NO(S) AFFECTED: 500-01 FINAL ASSY.

DESCRIPTION OF PROBLEM

1. HEATSINK COVER NOT AVAILABLE

REMEDY (NOTE ANY DEVIATIONS FROM SPEC.)

PACK UNITS WITHOUT HEATSINK COVER.
ASSOCIATED SCREWS TO BE SUPPLIED AS
A BATCH TO ENTERPRISE. (2 X 19-04)

NUMBER OF COMPUTERS AFFECTED : 100

COST IMPLICATION PER COMPUTER :

TOTAL COST IMPLICATION :

AUTHORISATION

PRODUCTION CO-ORDINATOR'S SIGNATURE

VENDOR'S Q.A. SIGNATURE

Colin Mooks

CA. Denton