

ORIGINATOR: COLIN MOOKS

DATE : 24.10.84

PART NO(S) AFFECTED: 500-01 FINAL ASSY

DESCRIPTION OF PROBLEM

1. JOYSTICK MECHANICALLY STICKS

REMEDY (NOTE ANY DEVIATIONS FROM SPEC.)

1. FIRST HUNDRED ONLY

DIMENSION OF 'PIP' AT UNDERSIDE OF JOYSTICK LEVER TO BE REDUCED BY 1MM USING CUTTERS.

NOTE: FUTURE QUANTITIES TO BE MODIFIED IN ACCORDANCE WITH REVISED AND UP-ISSUED DRAWING

NUMBER OF COMPUTERS AFFECTED : 100

COST IMPLICATION PER COMPUTER :

TOTAL COST IMPLICATION :

AUTHORISATION

PRODUCTION CO-ORDINATOR'S SIGNATURE

*Colin Mooks*

VENDOR'S Q.A. SIGNATURE

*G. St. P...*