

ORIGINATOR: COLIN MONKS

DATE : 24.10.84

PART NO(S) AFFECTED: 500-05 (PACKED UNIT)

DESCRIPTION OF PROBLEM

REQUIRED TO IDENTIFY ON MIC AND CARTON (04-02) WHETHER MIC BIASED FOR 256 COLUMN OR 80 COLUMN MODE.

REMEDY (NOTE ANY DEVIATIONS FROM SPEC.)

LABEL AS SHOWN BELOW, SUPPLIED BY ENTERPRISE TO BE ATTACHED TO UNDERSIDE OF BASE Moulding AND UNDERSIDE OF PRESENTATION CARTON (04-02) - LABEL TO BE AFFIXED NEATLY.

NOTE IF BIASED FOR 80 COLUMN MODE, STRIKE OUT 256, VICE VERSA. IF BOTH 80 COLUMN AND 256 COLUMN ACCEPTABLE, CIRCLE BOTH. CROSS REFER CONCESSION NO. 2.

NUMBER OF COMPUTERS AFFECTED

: 100 - ISSUE 3 BOARDS

COST IMPLICATION PER COMPUTER

:

TOTAL COST IMPLICATION

:

AUTHORISATION

PRODUCTION CO-ORDINATOR'S SIGNATURE

Colin Monks

VENDOR'S Q.A. SIGNATURE

G. A. Phelan

SUBSTANDARD VIDEO
BIASED 80/256
NOT FOR RESALE

3 LABEL SUPPLIED
BY ENTERPRISE.