

ORIGINATOR: COLIN MONKS

DATE : 25.10.84

PART NO(S) AFFECTED: 500-04.

DESCRIPTION OF PROBLEM

HEATSINK REQUIRED FOR NICK CHIP.

REMEDY (NOTE ANY DEVIATIONS FROM SPEC.)

FORM UP HEATSINK 02-10 AND SECURE USING
CYANOACRYLATE ADHESIVE.

TO BE FITTED AFTER FINANCIAL TEST
BEFORE SOAK TEST

NUMBER OF COMPUTERS AFFECTED : 100

COST IMPLICATION PER COMPUTER :

TOTAL COST IMPLICATION :

AUTHORISATION

PRODUCTION CO-ORDINATOR'S SIGNATURE

Colin Monks

VENDOR'S Q.A. SIGNATURE

G. Thompson