

ORIGINATOR: COLIN MONKS

DATE : 29.10.84

PART NO(S) AFFECTED: 500-04

DESCRIPTION OF PROBLEM.

SPEAKER IC (LM386) ON VERO BOARD REQUIRES  
DECOUPLING.

REMEDY (NOTE ANY DEVIATIONS FROM SPEC.)

ADD 1-OFF 100NF CAPACITOR P.N. 15-03  
BETWEEN PINS 4 AND 6 OF THE LM386.

NUMBER OF COMPUTERS AFFECTED : 100-OFF ISSUE 3 BOARDS

COST IMPLICATION PER COMPUTER :

TOTAL COST IMPLICATION :

AUTHORISATION

PRODUCTION CO-ORDINATOR'S SIGNATURE

*Colin Monks*

VENDOR'S Q.A. SIGNATURE

*S. Stephenson* 4/11/84