

ORIGINATOR: COLIN MONKS

DATE : 30.10.84

PART NO(S) AFFECTED: 500-01 FINAL ASSY.

## DESCRIPTION OF PROBLEM

JOYSTICK ACTION UNSATISFACTORY DUE TO DOME  
PROBLEM ON RUBBER KEYPAD.

## REMEDY (NOTE ANY DEVIATIONS FROM SPEC.)

CUT OUT SECTION OF KEYPAD - DRG. SHOWS  
MINIMUM AND MAXIMUM CUT AREAS. REPLACE WITH  
RUBBER RING P.N. 01-56

NUMBER OF COMPUTERS AFFECTED : 100 USING ISSUE 3

COST IMPLICATION PER COMPUTER :

TOTAL COST IMPLICATION :

AUTHORISATION

PRODUCTION CO-ORDINATOR'S SIGNATURE

Colin Monks

VENDOR'S Q.A. SIGNATURE

G. Stephenson 31/10/84