

ORIGINATOR: COLIN MONKS

DATE : 2.11.84

PART NO(S) AFFECTED: 500-04 (PCB ASSY)

DESCRIPTION OF PROBLEM

MARK SPACE ADJUSTMENT FOR INTERIM
NICK CHIP.

THIS IS A CONTINUATION OF
CONCESSION NOTE NO 2.

REMEDY (NOTE ANY DEVIATIONS FROM SPEC.)

ADJUST POT TO POSITION WHERE 80 COLUMN + 256
COLOUR ARE OF EQUAL QUALITY, THEN ADJUST (IF NEED)
SO THAT HALF THE UNITS ARE 80 COLUMN, THE OTHER
HALF 256 COLOUR. MARK ASTEC WITH ADJUSTMENT, AND
ALSO MARK LABEL ON UNDERSIDE OF UNIT WITH
80 IF BEST 80 COLUMN
256 IF BEST 256 COLOUR
80/256 IF NO ADJUSTMENT REQD FOR GOOD 80 COLUMN OR 256 COLOUR.

NUMBER OF COMPUTERS AFFECTED : 50-OFF ISS 4

COST IMPLICATION PER COMPUTER :

TOTAL COST IMPLICATION :

AUTHORISATION

PRODUCTION CO-ORDINATOR'S SIGNATURE

VENDOR'S Q.A. SIGNATURE

Colin Monks
